



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program

05/04/2006  
081241

Supervisor ADZ

Mine Name: ML 47821&46956/Cubical2

**Operator Name:**

Sprunger's Minerals  
Mike & Sandra Spunger  
PO Box 38054

Leamington, Ut 84638

**Inspector(s):** Tom Munson

**Other Participants:** None

**Mine Status:** inactive

**Permit number:** S230057

**Inspection Date:** 08/29/2006

**Time:** 3 PM

**Weather:** Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Perform an Annual inspection

**Directions to Site:**

Topaz Ampithreatre, West side of the Thomas Range, west of Delta

**Inspection Summary:**

The site has less than one acre of disturbance.

**Conclusions and Recommendations:**

The site will require a backhoe to reclaim, therefore the minimum \$5,400 should be assess to mobilize a piece of equipment.

**Inspector's Signature** Tom Munson

**Date:** 8/30/06

tm:jb

cc: Operator

Attachment: Photos

O:\M023-Juab\S0230057-Sprunger-3sites\Inspections\inspML47821-05042006.doc



SITLA LEASE ML 46956



08.29.2006 16:38



08.29.2006 16:39



08.29.2006 16:37



08.29.2006 16:38



SITUALEASE ML 46956

